

Tria Express Duet • Software Release Notes

Welcome to the Tria Express Duet V9.3.1 Software Release Notes. Please read this document to find important information on areas of Tria Express Duet that may not be covered in the Getting Started Guide or the User Help system.

CONTENTS

ZERSION HISTORY2	KNOWN ISSUES	20
VERSION 9.3.1 – SEPTEMBER 20242	VERSION 9.3.1 – SEPTEMER 2024	20
VERSION 9.3.0 – AUGUST 20242	VERSION 9.3.0 - AUGUST 2024	20
VERSION 9.2.4 – JULY 20246	VERSION 9.2.4 – JULY 2024	20
VERSION 9.2.3 – (SKIPPED)6	VERSION 9.2.3 (SKIPPED)	20
VERSION 9.2.2 – JUNE 20246	VERSION 9.2.2 – JUNE 2024	20
VERSION 9.2.1 – MARCH 20247	VERSION 9.2.1 – MARCH 2024	20
VERSION 9.2.0 – NOVEMBER 20238	VERSION 9.2.0 – NOVEMBER 2023	20
VERSION 9.1.0 – (SKIPPED)13	VERSION 9.1.0 (SKIPPED)	20
VERSION 9.0.2 - AUGUST 2023 13	VERSION 9.0.2 - AUGUST 2023	20
VERSION 9.0.1 – (SKIPPED)14	VERSION 9.0.1 (SKIPPED)	20
VERSION 9.0.0 – APRIL 2023 14	VERSION 9.0.0 - APRIL 2023	20
VERSION 8.3.2 – JANUARY 202317	VERSION 8.3.2 – JANUARY 2023	20
VERSION 8.3.1 - AUGUST 2022 17	VERSION 8.3.1 - AUGUST 2022	21
VERSION 8.3.0 – JUNE 2022 17	VERSION 8.3.0 – JUNE 2022	21
VERSION 8.2.4 – JUNE 2022	VERSION 8.2.4 – JUNE 2022	21
VERSION 8.2.3 – 8.2.1 (SKIPPED)	VERSION 8.2.3 — 8.2.1 (SKIPPED)	21
VERSION 8.2.0 – JULY 202118	VERSION 8.2.0 – JULY 2021	21
	GETTING HELP	22

Page 1 of 22



VERSION HISTORY

VERSION 9.3.1 – SEPTEMBER 2024

NEW FEATURES • (TRIA EXPRESS DUET PRODUCTION VIDEO SERVERS)

No New Features

BUGS FIXED • (TRIA EXPRESS DUET PRODUCTION VIDEO SERVERS)

No New Bug Fixes

VERSION 9.3.0 - AUGUST 2024

NEW FEATURES • (TRIA EXPRESS DUET PRODUCTION VIDEO SERVERS)

1. System: "Behind the scenes" Software License Tool

This new feature does not appear in or affect User Operations—but rather is background 'software hooks' used by the Ross Factory and Ross Support to validate and program Software Licenses for Tria products.

2. System: Video Card Firmware Updater App Changes

This app appears when upgrading the Software version in your Ross video server product that also requires updating the Firmware on the Ross Video Cards fitted in the video server.

This app had small tweaks to have the product logos removed and the Ross logo added.

3. System: Removed "Abekas" Logo and upgraded to latest "Ross" Grayscale Logo

These changes were made to the Tria Config, Tria Import, Tria Explorer, and the AsRun Log Report Generator apps.

4. System: Updated Third-Party Software Information in the "About" Dialogs


Third-Party License information and verbiage was updated to the most recent text within the "About" dialog within the Tria Explorer app.

5. Tria Config App: AMP Protocol Folder Setting for Sony Switcher Control

Sony Switchers have implemented the "media folder listing" command set in the AMP remote control protocol slightly out of specification — so it's different from how other switcher manufacturers have implemented these commands, including Ross.

On the RS422 tab, when "**AMP over Ethernet**" Protocol is active, a new "**Folder format**" radio button pair has been added near the bottom of the "**AMP Protocol Configuration**" section:






- Select the "Ross" radio button when controlling Tria from any Ross Switcher (or any Non-Sony branded Switcher) while using AMP protocol.
- Select the "**Sony**" radio button when controlling Tria from any Sony branded Switcher while using AMP protocol.


6. Tria Explorer App: Count-Down Timer while Playlist is Active

A new "Total Run Time" Count-Down timecode display has been added to the "On-Air" Playlist pane in the "Library" view in the Explorer app.


After a Playlist is first loaded into a player channel after clicking the "**AIR List**" button in the Playlist Editor, the new "Total Run Time" timecode is displayed in green text in the middle of the white-framed banner at the top of the Playlist pane:



It should be noted that if the "PVW-PGM playout option" is selected (**blue** checkbox enabled at top of Playlist pane), then the Total Run Time of the playlist takes into account the TRANS durations of all the items in the Playlist, and will reduce the Count-Down timecode:




While **actively** playing out the Playlist, this Count-Down timecode display will **count down** the total time (*towards zero*) as the content advances through the Playlist:



Page **3** of **22 ROS**



When the Playlist finished playing out all content, the Count-Down timer displays zero:



7. Tria Explorer App: Media File Export with Transcode now a "Background Task" using Software Transcoding

Prior to this V9.3 software release, any media file export that involved a transcode would require selecting a video channel transport which was used to perform the codec transcode operation.

Starting with this V9.3 software release, media file export operations that involve a transcode operation no longer require selecting a video channel and are now performed via a new "software transcode engine" that performs the transcode export "in the background" and without occupying a video channel transport.

8. Tria Explorer App: Media File Export FFmpeg Library Updated • with more 1080p Transcode Codecs

Media file exporting now supports the latest version of FFmpeg, which supports new DNxHD and MPEG-4 transcoding codecs while operating in 1080p video standards.

9. Tria Explorer App: Media File Export transcode with ProRes Codecs

Media file exporting function now supports a small variety of ProRes codecs while performing media file exports with transcode.

10. Tria Explorer App: Media File Export Failures now result in Error Message

If a media file export operation fails in the Tria Explorer app, a new "Export Failed" error message pop-up now appears with information on the cause of error.

Page **4** of **22**




11. Tria Explorer App: Clip Library New "Thumbnails View"

Two new buttons were added to the "Clip Library Ribbon" located at the top of the **Clip Library** listing: . These buttons control the "layout" of the contents in the Clip Library display, as follows:

Click the given "View" button to display the contents of the Clip Library in the desired view...

Original "**Text-Only**" View



New "**Thumbnails**" View



Page **5** of **22**



BUGS FIXED • (TRIA EXPRESS DUET PRODUCTION VIDEO SERVERS)

1. Tria Explorer: Export of Child Clips incorrectly ignored clipped IN point

When any Child clip is added to the Export Queue in Tria Explorer, the IN point of the Child clip was ignored with the Export incorrectly starting at the first frame of the Parent clip. This issue is now fixed, and Child clips are now correctly exported, starting at the first frame of the Child clip.

2. Tria Explorer: MultiViewer Audio Meters disabled while playing PVW>PGM Playlist

While playing a Playlist in a "PVW > PGM" **channel pair** in the Tria Explorer app, the Audio Meters displayed in that channel pair in the MultiViewer would incorrectly be 'disabled' upon every other TAKE operation in the Playlist playout. This bug did <u>not</u> affect the actual audio playout from the AES and/or HD-SDI OUT embedded audio; rather, it affected **only** the Audio Metering display. This bug also did <u>not</u> occur while playing out a Playlist in a **single** video channel.

VERSION 9.2.4 – JULY 2024

NEW FEATURES • (TRIA EXPRESS DUET PRODUCTION VIDEO SERVERS)

No New Features

BUGS FIXED • (TRIA EXPRESS DUET PRODUCTION VIDEO SERVERS)

1. System: Motherboard Intel Driver Issue causes rare Tria Explorer App Crash and/or degraded app performance

Fixed a slow memory leak caused by a change to driver for the Intel GPU integrated into the computer motherboard. This leak had potential to degrade the GPU performance and/or cause a very rare crash of the Tria Explorer App.

VERSION 9.2.3 – (SKIPPED)

This version number was skipped.

VERSION 9.2.2 – JUNE 2024

NEW FEATURES • (TRIA EXPRESS DUET PRODUCTION VIDEO SERVERS)


No New Features

BUGS FIXED • (TRIA EXPRESS DUET PRODUCTION VIDEO SERVERS)

1. Tria Explorer App: Clip Modify Dialog "Trim" Errors when using 'External Timecode'
When clips that were recorded with External Timecode are modified using the "Clip Modify" dialog:

Page 6 of 22 ROSS





...a couple of errors occurred:

- A manual timecode entry made within the **Trim In** entry field could not be set to any valid TC value of the External Timecode recorded into the clip.
- Clicking the **Reset Trim** button created a bogus timecode value. Once this happens, the length of the clip changed to 1 frame duration.

Both these issues are now resolved.

VERSION 9.2.1 - MARCH 2024

NEW FEATURES • (TRIA EXPRESS DUET PRODUCTION VIDEO SERVERS)

No New Features

BUGS FIXED • (TRIA EXPRESS DUET PRODUCTION VIDEO SERVERS)

1. System: RossTalk RECEIVE Commands Inoperable after "Abekas SE" Service Restart

When the Abekas SE service is manually restarted, the RossTalk service would not start up automatically afterward, resulting in RossTalk RECEIVE commands becoming disabled. This issue is now resolved; RossTalk service now automatically starts after restarting Abekas SE.

2. System: Chassis Service stops logging after a few hours

The background Chassis Service diagnostic logger would halt logging errors after a few hours machine operation. This issue is now resolved. The Chassis Service now continuously logs all errors.

3. File Import App: File Import causes Color Shift

An error in the color space conversion caused media file import to subtly shift colors of the imported media. This issue is now resolved; there is no longer any color shift when importing media files.

Page **7** of **22**



4. File Import App: App crash after several hundred media file imports

A slow memory leak caused the File Import app to crash after several hundred media files are imported. This issue is now resolved; the File Import app no longer crashes.

VERSION 9.2.0 – NOVEMBER 2023

NEW FEATURES • (TRIA EXPRESS DUET PRODUCTION VIDEO SERVERS)

5. Tria Config App: Change Default Image upon "Unload Video Channel"

Prior to V9.2 Software, whenever a video channel transport was "Unloaded" that channel would be automatically loaded with "Internal Color Bars".

A new feature has been added to the **Tria Config** app on the **Channels** tab to allow the User to change the image that gets loaded upon a Channel Unload operation. The choices are:

- Color Bars (Default)
- Black
- Stored Still/Clip from Clip Library

NOTE: The "Stored Still or Clip" selection will present <u>all</u> .clip files stored in the Clip Library, including clips that are in video standards *different* from the video standard the video server is currently operating in. If a still or clip is chosen that's in a *different* video standard, then when the Unload command is executed the "Color Bars" will be loaded instead (*because it's impossible to load a .clip file that's in another video standard*).

6. Tria Config App: RossTalk Protocol • Change Port Number

In the **Tria Config** app on the **RS422** tab, a new feature has been added to allow the "RossTalk port number" to be changed. The default port number is 7788.

The RossTalk port number can now be changed to a new port number ranging from 7788 to 7798 to help avoid duplicate RossTalk port numbers with other devices on the same Ethernet network.

7. Tria Remote Control: Added RossTalk Receive Command: Load Playlist

A new RossTalk Receive command has been added to load Playlist media content into specific video player channel(s), with the following syntax:

LUAD PLAYLIST (DVW-channel:)Dgm-channel:Dlavlistname	laylist in specific channel or channels amples of Load Playlist Command" below)
--	---

Examples of Load Playlist Command

LOAD_PLAYLIST B:A:Sports_Show

Loads playlist titled "Sports_Show" into ChA as PGM Player and with ChB as PVW Player. The first playlist item is loaded into ChA, while the second playlist item is loaded into ChB.



LOAD_PLAYLIST D:Good Morning Show

Loads playlist titled "Good Morning Show" into ChD as PGM Player; first item is loaded into ChD.

8. Tria Remote Control: Added RossTalk Receive Command: Loop Playlist

A new RossTalk Receive command has been added to loop all Playlist content in a specific video player channel, with the following syntax:

LOOP_PLAYLIST channel:mode	Enable Loop Playlist (see: "Examples of Loop Playlist Command" below)
	(see. Examples of Loop Flagilist Communic Delow)

Examples of Loop Playlist Command

These commands can be issued during playlist playout.

LOOP_PLAYLIST A:loop

Enables "loop" command for playlist currently loaded in ChA.

LOOP PLAYLIST A:off

Disables "loop" command for playlist currently loaded in ChA.

9. Tria Remote Control: RossTalk Receive Commands: 'forward slash' to indicate 'Folder'

While using RossTalk Receive commands that can include 'folders' and 'subfolders' in the video server's Clip Library, the 'forward slash' character (/) is now allowed, in addition to the 'back slash' character (\), as has always been the case.

Example:

(H:\Video) SPORTS\HOCKEY\Finals or (H:\Video) SPORTS\\HOCKEY\\Finals

Can now be simply:

(H:\Video) SPORTS/HOCKEY/Finals

RossTalk Receive Commands affected by this change:

CUE channel:clipname	Load <i>clipname</i> on <i>channel</i>
CUE channel:clipname:position	Load clipname on channel and seek to position
PLAY channel:clipname	Load <i>clipname</i> and start playing
PLAY channel:clipname:position	Load clipname and start playing from position
LOAD_PLAYLIST (pvw-channel:)pgm-channel:playlistname	Load <i>playlist</i> in specific <i>channel</i> or <i>channels</i>

10. Tria Remote Control: Added RossTalk Receive Command: TAKE

A new RossTalk Receive command has been added to transition ("take") media content within specific video player channel, with the following syntax:

TAKE channel	Take (transition) clip content in <i>channel</i>
TAKE Chumer	(see: "Examples of TAKE Command" below)

Examples of TAKE Command

TAKE A



With the Tria Explorer app configured with two PGM Players while a Playlist is "ON-AIR" in the channel pair (ChA=PGM / ChB=PVW): Swaps PVW content of the Playlist from ChB into PGM ChA, and advances the Playlist forward by one item.

TAKE C

With the Tria Explorer app configured with two PGM Players while a Playlist is "ON-AIR" in the channel pair (ChC=PGM / ChD=PVW): Swaps PVW content of the Playlist from ChD into PGM ChC, and advances the Playlist forward by one item.

11. Tria Remote Control: Added RossTalk Receive Command: UP_ONE_ITEM

A new RossTalk Receive command has been added to move an active Playlist's "current item highlighting cursor" UP by one item in the Playlist, with the following syntax:

UP_ONE_ITEM channel	Move Playlist "current item highlighting cursor" for playlist active in <i>channel</i> UP by one
	item (see: "Example of UP_ONE_ITEM Command" below)

Examples of UP_ONE_ITEM Command

UP_ONE_ITEM B

While Playlist is loaded in ChB as (PVW) with ChA as (PGM): moves the "current item highlighting cursor" UP by one item within the playlist that's currently active in ChB.

12. Tria Remote Control: Added RossTalk Receive Command: DOWN ONE ITEM

A new RossTalk Receive command has been added to move an active Playlist's "current item highlighting cursor" DOWN by one item in the Playlist, with the following syntax:

DOWN_ONE_ITEM channel	Move Playlist "current item highlighting cursor" for playlist active in <i>channel</i> DOWN by
	one item
	(see: "Example of DOWN_ONE_ITEM Command" below)

Examples of DOWN_ONE_ITEM Command

DOWN ONE ITEM B

While Playlist is loaded in ChB as (PVW) with ChA as (PGM): moves the "current item highlighting cursor" DOWN by one item within the playlist that's currently active in ChB.

13. Tria Remote Control: Added RossTalk Receive Command: RECUE_TO_FIRST_ITEM

A new RossTalk Receive command has been added to move an active Playlist's "current item highlighting cursor" to FIRST item in the Playlist, with the following syntax:

RECUE_TO_FIRST_ITEM channel	Move Playlist "current item highlighting cursor" for playlist active in <i>channel</i> to FIRST item
	(see: "Example of RECUE_TO_FIRST_ITEM Command" below)

Page **10** of **22 ROSS**



Examples of RECUE_TO_FIRST_ITEM Command

RECUE_TO_FIRST_ITEM B

While Playlist is loaded in ChB as (PVW) with ChA as (PGM): moves the "current item highlighting cursor" to FIRST item within the playlist that's currently active in ChB.

If you want the newly highlighted playlist item to transition into the PGM player, you'll need to follow this RECUE command with a TAKE command.

14. Tria Remote Control: Added RossTalk Receive Command: EJECT_PLAYLIST

A new RossTalk Receive command has been added to unload (EJECT) a Playlist that's currently loaded in the specified video channel, with the following syntax:

	Unloads (Ejects) Playlist that's currently
EJECT_PLAYLIST channel	loaded in channel (see: "Example of EJECT_PLAYLIST Command" below)
	Communa below)

Examples of EJECT_PLAYLIST Command

EJECT_PLAYLIST A

While Playlist is loaded in ChB as (PVW) with ChA as (PGM): halts playout of the active Playlist but keeps the currently playing item in ChA (PGM) playing out.

To completely clear the Playlist from all playout channels, follow with another command:

EJECT PLAYLIST A

— or —

EJECT A

BUGS FIXED • (TRIA EXPRESS DUET PRODUCTION VIDEO SERVERS)

1. File Import: Photoshop (PSD) media file support

Fixed bug that prevented Photoshop files (.PSD) from being imported. These files now import.

2. Tria Explorer App: "Clip Trim" functions broken in "Clip Modify" dialog window

When using the "Clip Modify" dialog window with the "Trim" tab selected (*shown below*), the "Trim In" and "Trim Out" functions did not operate correctly, while the associated QWERTY keyboard shortcuts did operate correctly. These bugs are now fixed.


Page **11** of **22 ROS**



3. Tria Explorer App: LOAD Button "Grayed Out" when Locking/Unlocking a Channel Transport

When Tria Explorer app is closed/quit while a "Channel Transport" is locked (via the CTRL+Mouse Click lock function), then launch Tria Explorer app again and unlock the Channel Transport, the Clip Load button is grayed out and inaccessible. The only way to regain access to the Clip Load button it to close/quit Tria Explorer again while the Channel Transport is unlocked.

This bug is now fixed.



4. Tria Explorer App: Using "GoTo/Seek to Timecode" function with imported clips, seeks to wrong timecode

This bug is now fixed.

In the Tria Explorer app, Users can easily seek to a desired timecode point within the currently loaded clip while a clip is loaded in a given video channel transport:

- a) Double-Click the "Count Up" timecode (the "lower" green timecode number); this changes that timecode display into a "Timecode Entry Field".
- b) Type value of the desired timecode into numeric keypad on QWERTY.
- c) Tap ENTER on QWERTY to "seek" or "goto" the defined timecode within the currently loaded clip.

This works fine if the clip loaded in the channel was recorded via HD-SDI video input.

This procedure does NOT work if the clip loaded in the channel transport was imported via the File Import app. The procedure will "seek" to an incorrect timecode value.

And if the imported clip is parked on the first frame this "seek" operation does NOTHING.

This bug is now fixed.

5. Tria Explorer App: Unable to create Child Clips from previously used Clip Name

When a clip is created with a given Clip Name, you're able to create Child Clips from that Parent Clip.

However, when these Parent and Child Clips are all deleted, and then a newer Parent Clip is recorded with the *exact same* Clip Name as the old Parent Clip that was deleted earlier, then it is impossible to create Child Clips from this newer Parent Clip.

This bug is now fixed.

Page **12** of **22 ROSS**



6. Tria Explorer App: Rare Crash

Fixed app crash that was quite rare but happened most often while playing out Playlists of Stills.

7. Tria Explorer App: Audio Meter Scaling Changes

Audio Meters level scaling was adjusted to correct a 12dB offset with respect standard audio reference scaling.

VERSION 9.1.0 – (SKIPPED)

This version number was skipped.

VERSION 9.0.2 – AUGUST 2023

NEW FEATURES • (TRIA & TRIA+ PRODUCTION VIDEO SERVERS)

No New Features

BUGS FIXED • (TRIA & TRIA+ PRODUCTION VIDEO SERVERS)

1. AMP Protocol: "Get Clip List" Command Broken

The AMP protocol command "Get Clip List" returned only one clip from the Clip Library, no matter how many clips are stored. This bug is now fixed.

2. All Remote-Control Protocols:

Improved command latency of video servers running in video standards below 30Hz.

3. Tria Explorer App: Very Rare App Crash

When running a Playlist with a series of stills in a loop for several hours non-stop, the Tria Explorer App would eventually crash. This bug is now fixed.

4. File Import App: Video not Centered upon file import

When importing media files with a video aspect ratio that's different from the current operating video standard, the media file's video would not be 'centered' in the raster. This bug is now fixed, and the video is now centered in the raster.

5. File Import App: Photoshop media files (.psd) do not import

When a still media file with the .psd file extension was imported, an error message resulted, and the file was not imported. This bug is now fixed.

6. File Import App: Black frame added to end of clip

For media files created with certain video codecs, upon import of these media files an extra frame of black was added to the end of the clip. This bug is now fixed.

Page **13** of **22 ROSS**



VERSION 9.0.1 – (SKIPPED)

This version number was skipped.

VERSION 9.0.0 - APRIL 2023

NEW FEATURES • (TRIA EXPRESS DUET PRODUCTION VIDEO SERVER)

1. Software Licensing Feature

Added new feature that "keys" a new software license for the "Tria Software Suite" to the Tria Express Duet motherboard serial number.

Learn more about the purpose behind this new software license.

2. Support clips longer than 24 hours

Increased maximum duration of SDI input recordings to go beyond 24-Hours and up to currently available media storage open space.

3. 14-Tracks of Embedded Audio

Increased the number of embedded audio tracks from 8-tracks to 14-tracks.


4. Audio Level Metering Displays in Tria Explorer MultiViewer

Features of the new Audio Metering Displays:

- a) **Tria Explorer app**: The new Audio Metering Displays can be superimposed over the active video image within the video panes independently for each video channel, but only within the MultiViewer display (when VIEWER is active).
 - Position & Opacity of each Audio Meter Display can be set to one of six locations within each video pane through the "Audio Meters" tab in the General Configuration dialog window:

Page **14** of **22**





- b) The "ALT+M" keyboard shortcut can be used at any time to toggle ON or OFF all the Audio Meter Displays in the **Tria Explorer** app.
- c) The number of audio tracks displayed in the Audio Metering Displays is dictated by:
 - How many audio tracks exist in the clip currently loaded in the given video channel (during PLAY operations)
 - How many audio tracks exist in the clip currently recording in the given video channel (during LIVE EE and RECORD operations)

5. Added Quad Viewer HD-SDI Output


Version 9.0.0 has enabled the "Quad Viewer" HD-SDI output. On the rear of the Tria Express Duet chassis in the array of BNC connectors, the Quad Viewer HD-SDI output is now present on the BNC connector located at the lower left corner, which most likely has a BLACK rubber cap on it.

Simply remove the BLACK cap from the BNC connector and connect an HD-SDI monitor to this BNC to display the new Quad Viewer output.

Below is a label of the BNC I/Os with the Quad Viewer labeled in lower left:

Page **15** of **22**





NOTE: If you would like to receive a self-adhesive stick-on BNC I/O label to apply over the existing label on the Top Cover of your Tria Express Duet chassis:

- a) Submit a General Request to Ross Support using this online form (URL for the form is shown below)
- b) In the form, ask for this Part Number & Description:4600GR-200-02 (Tria Express DUET Chassis Rear Panel Label)
- c) Be sure to provide the Ross serial number of your Tria Express Duet chassis (enter number into "Asset Serial Number" field in the Request form)
- d) Enter all your contact and shipping information in the Request form

(https://support.rossvideo.com/hc/en-us/requests/new?ticket form id=360000661031)

BUGS FIXED • (TRIA EXPRESS DUET PRODUCTION VIDEO SERVER)

1. Tria Explorer App: Keywords Column in Clip Library

Fixed issue in which "Keywords" column could not be made visible in Library view.

Keywords are now also searched with a Clip Library search operation.

2. Tria File Import App: Importing MXF media files with VANC data Corrupts Video

Fixed an issue in which importing AVC-Intra MXF media files containing VANC data (such as Closed-Caption data) would sometimes corrupt video—resulting in "tearing" in the video image during playback.

3. Tria File Import App: MXF media files with VANC data Truncated after 5 Minutes

Fixed an issue in which importing AVC-Intra MXF media files containing VANC Closed-Caption data would have the Closed-Caption data truncated after 5-Minutes into the clip playback.

4. Tria Explorer App: Added Window Title of Undocked MultiViewer

Now displays "Tria Express Duet MultiViewer" in Windows title bar.

5. Security Fix: Ethernet Port 8080 no longer has Remote Access

Fixed issue to restrict remote access to Ethernet port 8080.

Page **16** of **22 ROS**



VERSION 8.3.2 - JANUARY 2023

NEW FEATURES • (TRIA & TRIA+ PRODUCTION SERVERS)

No New Features

BUGS FIXED • (TRIA & TRIA+ PRODUCTION SERVERS)

1. AMP Protocol: Clip Library Listing caused system crash in "certain cases"

Fixed an issue in which clips that are named in certain ways would result in a Tria Express Duet system crash when the "Get Clip List" command was issued from AMP remote controllers.

VERSION 8.3.1 – AUGUST 2022

NEW FEATURES • (TRIA EXPRESS DUET PRODUCTION SERVER)

No New Features

BUGS FIXED • (TRIA EXPRESS DUET PRODUCTION SERVER)

1. Tria Explorer app: Unable to re-arrange items in Playlist while Playlist Editor is active

Fixed Bug: Applies to the Playlist Editor in the Tria Explorer application; items could not be rearranged with drag-and-drop operation.

VERSION 8.3.0 – JUNE 2022

NEW FEATURES • (TRIA EXPRESS DUET PRODUCTION SERVER)

1. System: New Video Standard Frame Rates

These new frame rates were added to the **1080p** video standard:

1080p60 ("True 60p") | 1080p30 | 1080p29.97 | 1080p25 | 1080p24 | 1080p23.98

2. Tria Explorer app: New "Clip Networking" Feature

Enables two or more Tria Express Duet video servers to be interconnected via 1G Ethernet, with clip files played across the network from one Tria Express Duet server and into another Tria Express Duet server.

To enable this feature: In Tria Config app on the Video tab, enable the "Net Video" checkbox on <u>all</u> Tria Express Duet servers interconnected via 1G Ethernet network.

3. Tria Explorer app: Search now 'Auto-Expands' Folder(s) with matching clips/playlists/sub-folders

When searching for text in Tria Explorer, the Clip Library now automatically expands any folder containing matching clips, playlists, and sub-folders.

Page **17** of **22**



BUGS FIXED • (TRIA EXPRESS DUET PRODUCTION SERVER)

1. System: Functional hang-up after deleting .clip files via Tria Explorer app and via remote control interfaces.

In rare cases under very particular conditions, deleting a .clip file via the Tria Explorer app or from remote control interfaces would then cause the controlling app to "functionally hang"; the only remedy was to quit and re-start the controlling app. This bug is now fixed.

2. Tria Explorer app: Export of .clip Files stored on Drive Volumes other than "H:\Video"

Fixed issue where the Tria Explorer application would not export content from ".clip" files stored on drive volumes other than "H:\".

3. Tria Explorer app: Playlists containing "missing items" now skips those items

When a Playlist contains "missing items" (items in which the underlying clip files were either renamed, deleted, or moved to another folder), the Playlist playout would halt on the missing item(s). This bug is now fixed.

4. Tria Import app: Failure to 'close' MXF media file after import during "native" codec import

This bug would leave the source MXF media files "open" from the file system point of view, preventing other applications from moving, deleting, re-naming, or otherwise altering the source media files after they were imported. This bug is now fixed.

VERSION 8.2.4 – JUNE 2022

NEW FEATURES • (TRIA EXPRESS DUET PRODUCTION SERVER)

1. System: Windows Security Patch

Added work-around security patch for Microsoft Windows CVE-2022-30190.

VERSION 8.2.3 – 8.2.1 (SKIPPED)

These version numbers were skipped.

VERSION 8.2.0 – JULY 2021

NEW FEATURES • (TRIA EXPRESS DUET PRODUCTION SERVER)

1. Tria Explorer app: Clip Countdown Added to Viewer

Previously, in the "Viewer" tab of Tria Explorer, the only timecode values on display were "count-up" timecode values. An option has now been added to change the "count-up" timecode in the Viewer to "count-down" (or time remaining) timecode. This option can be turned on or off, on a per-channel basis, in Tria Config app's "Timecode" tab.

Page **18** of **22 ROS**



2. System: VANC Data

Tria Express Duet will now maintain VANC (vertical ancillary) data during baseband video recording and playout, allowing for VANC data such as closed captions to be preserved. This only applies to baseband recording, and *not* video file import.

BUGS FIXED • (TRIA EXPRESS DUET PRODUCTION SERVER)

1. System: Audio Track Errors

Fixed issue that caused small errors in the audio tracks of baseband recordings.

2. System: RS422 Channel Assignments Ignored

Fixed issue where the channel assignments for DB9 RS422 serial control ports were ignored.

3. Tria Config App: Channel Configuration Labels Error

Fixed issue where channels configurations in Tria Config application were incorrectly labeled.

4. Tria Config App: RS422 Ports Label Errors

Fixed issue where the RS422 ports were incorrectly labeled in Tria Config application.

5. Tria Config App: Timecode Overlay

Fixed issue where timecode overlay was not available for ChC and ChD in Tria Config application.

Page **19** of **22**



KNOWN ISSUES

VERSION 9.3.1 – SEPTEMER 2024

No Known Issues

VERSION 9.3.0 - AUGUST 2024

No Known Issues

VERSION 9.2.4 – JULY 2024

No Known Issues

VERSION 9.2.3 (SKIPPED)

This version number was skipped.

VERSION 9.2.2 - JUNE 2024

No Known Issues

VERSION 9.2.1 - MARCH 2024

No Known Issues

VERSION 9.2.0 - NOVEMBER 2023

No Known Issues

VERSION 9.1.0 (SKIPPED)

This version number was skipped.

VERSION 9.0.2 – AUGUST 2023

No Known Issues

VERSION 9.0.1 (SKIPPED)

This version number was skipped.

VERSION 9.0.0 - APRIL 2023

No known issues.

VERSION 8.3.2 – JANUARY 2023

Page **20** of **22**

No known issues.

ROSS



VERSION 8.3.1 - AUGUST 2022

No known issues.

VERSION 8.3.0 – JUNE 2022

No known issues.

VERSION 8.2.4 – JUNE 2022

1. Missing Video Panes in DashBoard V9.5 and above

Video panes will not appear in a DashBoard panel running on the Tria video server itself. If the DashBoard app software version is V9.4 or below, the video panes operate properly.

VERSION 8.2.3 — 8.2.1 (SKIPPED)

These version numbers were skipped.

VERSION 8.2.0 – JULY 2021

1. Media File Import: Field Overlap Error in 1080i50 Content

As of Software Version 8.1.0 there is an issue when importing 1080i50 content that can cause fields to appear to overlap, creating a blurred image.

2. Tria Explorer: VK Channel Pair Error

As of Software Version 8.2.0 there is no way to record a clip with video+key if channels A and B are configured as a VK channel pair. This functionality will be added in a later release. The workaround for this issue is to bring in video+key content via the file import application, and not via baseband video input.

Page **21** of **22 ROSS**



GETTING HELP

- Ross Online Tria Express Duet Help on the Web: Tria Express Duet Online Help
- Ross Support on the Web: https://support.rossvideo.com/hc/en-us
- Our 24-hour hotline service provides access to technical expertise around the clock. After-sales service and technical support is provided directly by Ross Video personnel...
 - During business hours (Eastern Standard Time):

Ross Technical Support personnel are available by telephone:

- Technical Support: (+1) 613-652-4886
- After Hours Emergency: (+1) 613-349-0006
- After hours and on weekends:

Emergency technical support is available. A telephone-answering device will provide the names and phone numbers of technical support and field service personnel who are on call. Ross staff are available to react to any problem and to do whatever is necessary to ensure customer satisfaction.

• Serious issues needing urgent attention and tracking:

Please ensure you are given a ticket number and refer to this number in follow-up communications.

Page **22** of **22**