


# XPression

## Basic Cabling

⚠ CAUTION: Before you set up and operate this product, see the “Important Safety Instructions” in your Manual.



- 1 Use the supplied Rack Mount Kit to mount the XPression system in a 19" EIA equipment rack.  
*For information on installing the XPression chassis in a rack, see the provided document “Installing the Chassis in a Rack”.*
- 2 Plug the supplied Keyboard into one of the **USB** ports.
- 3 Plug the supplied Mouse into one of the **USB** ports.
- 4 Connect a Monitor (customer supplied) to any of the four display ports.  
*KVM extenders (customer supplied) are required when the XPression system monitor, keyboard, and mouse are located remotely from the rack room.*
- 5 Plug an Ethernet cable from your Local Area Network into either the **1G (a)** or **10G (b) Ethernet** port.  
*XPression systems can be connected to the Internet or restricted production network. The network connection is also used to distribute assets and for the RossTalk/Smart GPI feature.*
- 6 Connect power cords from the AC ports on the XPression system to the mains power.  
*XPression system power supplies are auto-sensing and can use either 110 VAC or 220 VAC.*