

Abekas **Tria News** Software Update Release Notes Software Version: V6.3.7



Document Revised: April 23, 2019

Bug Fixes

A. **“Click to Play” Delay Reduced**

- In previous versions of software, the time it took for a clip to begin playout after clicking the “Play” button (or executing the “Play” command from remote control via Ethernet or RS422) was about 18 frames in time.
- This delay has been reduced to 5 frames. Therefore, the response of clicking play, and seeing the start of clip playout is now almost instantaneous.

B. **Occasional Clip Playout Stutter while other Channels are Loading Clip(s)**

- In previous versions of software, if a given playout channel was actively playing a clip, the playout of this clip could experience a “stutter” (repeated frames of video)—which was caused by the “clip load” operations in other video playout channels.
- This bug is now fixed in V6.3.7 software.

New Features

No New Features in this software release.

END of DOCUMENT