



# Tria & Tria+ Production Server • Software Release Notes

Welcome to the Tria and Tria+ Release Notes. Please read this document to find important information on areas of Tria and Tria+ that may not be covered in the Getting Started Guide or the User Help system.

## CONTENTS

<b>VERSION HISTORY</b> .....	<b>2</b>	VERSION 7.1.12 – SEPTEMBER 2020.....	9
VERSION 8.3.5 – APRIL 2026.....	2	VERSION 7.1.11 – AUGUST 2020.....	9
VERSION 8.3.4 – MARCH 2024 .....	2	VERSION 7.1.10 – MARCH 2020 .....	9
VERSION 8.3.3 – AUGUST 2023.....	3	VERSION 7.1.7 THROUGH VERSION 7.1.9.....	10
VERSION 8.3.2 – JANUARY 2023.....	3	VERSION 7.1.6 – AUGUST 2020.....	10
VERSION 8.3.1 – AUGUST 2022.....	3	VERSION 7.1.5 – NOVEMBER 2019 .....	10
VERSION 8.3.0 – JUNE 2022.....	4	VERSION 7.1.4 – NOVEMBER 2019 .....	10
VERSION 8.2.4 – JUNE 2022.....	5	VERSION 7.1.3 – OCTOBER 2019 .....	11
VERSION 8.2.3 – (SKIPPED).....	5	<b>KNOWN ISSUES</b> .....	<b>12</b>
VERSION 8.2.2 – FEBRUARY 2022 .....	5	VERSION 8.3.1 – AUGUST 2022.....	12
VERSION 7.1.19 THRU 8.2.1 – (SKIPPED) .....	7	VERSION 8.3.0 – JUNE 2022.....	12
VERSION 7.1.18 – JULY 2021 .....	7	VERSION 8.2.4 – JUNE 2022.....	12
VERSION 7.1.17 – JULY 2021 .....	7	VERSION 8.2.3 — 8.2.1 (SKIPPED).....	12
VERSION 7.1.16 – JUNE 2021 .....	8	VERSION 8.2.2 – FEBRUARY 2022 .....	12
VERSION 7.1.15 – MAY 2021 .....	8	VERSION 7.1.14 – APRIL 2021.....	13
VERSION 7.1.14 – APRIL 2021 .....	8	<b>GETTING HELP</b> .....	<b>14</b>
VERSION 7.1.13 – NOVEMBER 2020.....	9		

## VERSION HISTORY

### VERSION 8.3.5 – APRIL 2026

#### NEW FEATURES • (TRIA & TRIA+ REPLAY SYSTEMS)

No New Features

#### BUGS FIXED • (TRIA & TRIA+ REPLAY SYSTEMS)

##### 1. Import: Some imported clips had missing audio

Fixed an issue where the audio was incorrectly muted at the start of imported clips.

##### 2. Import: Imported MP4 clips had an extra black frame

Fixed an issue where imported MP4 clips had an extra frame of black incorrectly added.

##### 3. Export: Exporting child clips resulted in incorrect timecodes

Fixed an issue where, when creating and exporting a child clip with a modified timecode, the exported clip's timecode would be incorrect.

##### 4. Export: Trimmed child clips were exported incorrectly

Fixed an issue where, when creating and trimming a child clip, the exported clip incorrectly used the first frame of the original clip rather than the first frame of the trimmed child clip.

### VERSION 8.3.4 – MARCH 2024

#### NEW FEATURES • (TRIA & TRIA+ REPLAY SYSTEMS)

No New Features

#### BUGS FIXED • (TRIA & TRIA+ REPLAY SYSTEMS)

##### 1. Import: Last frame of a clip copied as the first frame

Fixed an issue where the last frame of an imported clip would be copied as the first frame.

##### 2. Import: Imported clips appearing incorrectly

Fixed an issue where imported clips could appear shifted to the right.



### 3. Mira Replay App: Child clips unable to be created

Fixed an issue where child clips were unable to be created.

## VERSION 8.3.3 – AUGUST 2023

### NEW FEATURES • (TRIA & TRIA+ REPLAY SYSTEMS)

No New Features

### BUGS FIXED • (TRIA & TRIA+ REPLAY SYSTEMS)

#### 1. Import: Still images not centered

Fixed an issue where imported still images were not always imported correctly and could appear uncentered.

#### 2. Import: PSD files do not import

Fixed an issue where attempting to import .PSD files caused an error to occur.

#### 3. PIERO: Deleted clips remained visible

Fixed an issue where clips that were deleted from the Clip Register were still visible in the connected PIERO interface.

#### 4. Mira Replay App: Server clips were not exported

Fixed an issue where server clips in a playlist were not included in the exported media file when a Playlist Melt operation was performed on the playlist.

## VERSION 8.3.2 – JANUARY 2023

### NEW FEATURES • (TRIA & TRIA+ PRODUCTION SERVERS)

No New Features

### BUGS FIXED • (TRIA & TRIA+ PRODUCTION SERVERS)

#### 1. AMP Protocol: Clip Library Listing caused system crash in “certain cases”

Fixed an issue in which clips that are named in certain ways would result in a Tria system crash when the “Get Clip List” command was issued from AMP remote controllers.

## VERSION 8.3.1 – AUGUST 2022

### NEW FEATURES • (TRIA & TRIA+ PRODUCTION SERVERS)

No New Features

**BUGS FIXED • (TRIA & TRIA+ PRODUCTION SERVERS)**

**1. Tria Explorer app: Unable to re-arrange items in Playlist while Playlist Editor is active**

Fixed Bug: Applies to the Playlist Editor in the Tria Explorer application; items could not be rearranged with drag-and-drop operation.

**VERSION 8.3.0 – JUNE 2022**

**NEW FEATURES • (TRIA & TRIA+ PRODUCTION SERVERS)**

**1. Tria Explorer app: Search now ‘Auto-Expands’ Folder(s) with matching clips/playlists/sub-folders**

When searching for text in Tria Explorer, the Clip Library now automatically expands any folder containing matching clips, playlists, and sub-folders.

**BUGS FIXED • (TRIA & TRIA+ PRODUCTION SERVERS)**

**1. System: Corrupted audio output while operating in video standards with 29.97Hz frame rate**

Fixed issue of corrupted audio playback in the embedded and AES audio outputs while operating the video server in a video standard with the 29.97Hz frame rate.

**2. System: Audio-Video timing error while operating in video standards with frame rates below 30Hz**

Fixed issue of audio-video timing error during clip playback while operating the video server in a video standard with the frame rates below 30Hz.

**3. System: Clips created in Video Standards with frame rates below 30Hz would display incorrect timecode**

This bug is now fixed.

**4. System: Functional hang-up after deleting .clip files via Tria Explorer app and via remote control interfaces.**

In rare cases under very particular conditions, deleting a .clip file via the Tria Explorer app or from remote control interfaces would then cause the controlling app to “functionally hang”; the only remedy was to quit and re-start the controlling app. This bug is now fixed.

**5. Tria Explorer app: Export of .clip Files stored on Drive Volumes other than “H:\Video”**

Fixed issue where the Tria Explorer application would not export content from “.clip” files stored on drive volumes other than “H:\”.

## 6. Tria Explorer app: Playlists containing “missing items” now skips those items

When a Playlist contains “missing items” (items in which the underlying clip files were either re-named, deleted, or moved to another folder), the Playlist playback would halt on the missing item(s). This bug is now fixed.

## 7. Tria Import app: Failure to ‘close’ MXF media file after import during “native” codec import

This bug would leave the source MXF media files “open” from the file system point of view, preventing other applications from moving, deleting, re-naming, or otherwise altering the source media files after they were imported. This bug is now fixed.

## VERSION 8.2.4 – JUNE 2022

### NEW FEATURES • (TRIA & TRIA+ PRODUCTION SERVERS)

#### 1. System: Windows Security Patch

Added work-around security patch for [Microsoft Windows CVE-2022-30190](#).

## VERSION 8.2.3 – (SKIPPED)

This version number was skipped.

## VERSION 8.2.2 – FEBRUARY 2022

### NEW FEATURES • (TRIA & TRIA+ PRODUCTION SERVERS)

#### 1. System: New Video Standard Frame Rates (Tria & Tria+ with AVC-Intra Hardware Only)

These new frame rates were added to the **1080p** video standard:

1080p60 (“True 60p”) | 1080p30 | 1080p29.97 | 1080p25 | 1080p24 | 1080p23.98

#### 2. System: Timecode Chase Input

Changed Timecode Chase feature to use ‘stereo audio input’ on computer motherboard instead of ‘mono audio input’ to allow Timecode Chase to work on legacy motherboards.

#### 3. System: “As Run Log” Report Generator app

Added this new feature to filter, display, and generate a PDF or CSV file of media clips that have been played in any video channel for up to the previous 90 days.

#### 4. System: RossTalk RECEIVE Commands

Added new feature to support RossTalk protocol “receive” commands via Ethernet to control video channels in the Tria production video server.

#### 5. System: VANC record and play in 720p & 1080p video standards (Tria & Tria+ with AVC-Intra Hardware Only)

Expanded the ability for record and playback of VANC data contained within the SDI video I/O pathways **in 720p and 1080p video standards**—so VANC data such as closed-captioning, HDR flags, etc. are preserved during base-band record and playback on the SDI video I/O pathways.

#### 6. Tria Import app: Updated MXF Media File Libraries to latest version

These updated MXF libraries improves handling of MXF media files during Import and Export operations when the MXF contains native video codec essence.

### BUGS FIXED • (TRIA & TRIA+ PRODUCTION SERVERS)

#### 1. Tria Explorer app: “Create Child Clip” from non-existent angles in a multi-angle .clip file

Angles that were not present in the .clip file would be offered for creating a Child clip. These angles are now dimmed and un-selectable in the pop-up menu that appears when you right-click on this .clip file and select > “Create child clip from angle”.

#### 2. System: Erroneous Error Messages about assigning RS422 to a Video Channel

Fixed an issue in which erroneous error messages would appear asking the User to assign an RS422 port to a video channel.

#### 3. Tria Import app: Media Files Imported with “Frame of Black” at Start or End of .clip file

Fixed an issue with the Media File Import app (using FFmpeg libraries) when importing certain content that caused a frame of Black to be included at either the start or end of the imported .clip file.

#### 4. Tria Import app: Media Files Imported with “Audio Glitches” in .clip file

Fixed an issue that caused “audio glitches” when importing media files containing audio with a 44.1kHz sample rate.

#### 5. Tria Import app: Media Files Imported with Incorrect Aspect Ratio

Fixed an issue with the Media File Import app (using FFmpeg libraries) when importing media files with an aspect ratio different from the currently active video standard. The File Import app now anchors video into upper-left corner, instead of resizing it.

#### 6. System: AMP Protocol – Root folder now called “Default” in command replies

Some external third-party applications require this exact name for the ‘root folder’ (a.k.a. “H:\Video” folder) in order to function properly.

**7. System: AMP Protocol – Received Command “No Reply”**

Fixed an issue in which received AMP protocol commands sometimes resulted in ‘no reply’ to the external controlling device.

**8. System: AMP Protocol – Record Cue Command when used with ‘long’ clip name**

Fixed an issue where the AMP protocol RECORD\_CUE command would fail when a ‘long’ clip name was specified with the command.

**VERSION 7.1.19 THRU 8.2.1 – (SKIPPED)**

These version number series were skipped.

**VERSION 7.1.18 – JULY 2021**

**NEW FEATURES • (TRIA & TRIA+ PRODUCTION SERVERS)**

No New Features

**BUGS FIXED • (TRIA & TRIA+ PRODUCTION SERVERS)**

- 1. Embedded Timecode Out Missing in Quad Link SDI video streams while operating in UHD-4K video standard**

**(Tria & Tria+ with AVC-Intra Hardware Only)**

Repaired the missing timecode out (fixed on “second and third video boards” ChE-ChL).

**VERSION 7.1.17 – JULY 2021**

**NEW FEATURES • (TRIA & TRIA+ PRODUCTION SERVERS)**

No New Features

**BUGS FIXED • (TRIA & TRIA+ PRODUCTION SERVERS)**

- 1. Embedded Timecode Out Missing in Quad Link SDI video streams while operating in UHD-4K video standard**

**(Tria & Tria+ with AVC-Intra Hardware Only)**

Repaired missing timecode out (but fixed only on “first video board” ChA-ChD).



## VERSION 7.1.16 – JUNE 2021

### NEW FEATURES • (TRIA & TRIA+ PRODUCTION SERVERS)

#### 1. **Firmware Update to support HDR VPID metadata in UHD-4K Video Standards (Tria & Tria+ with AVC-Intra Hardware Only)**

Specific FPGA firmware update to add HDR VPID metadata on the SDI video I/Os during UHD-4K video standard operation. This applies specifically to the “Quad-Link” 3G SDI I/Os only.

### BUGS FIXED • (TRIA & TRIA+ PRODUCTION SERVERS)

No Bug Fixes

## VERSION 7.1.15 – MAY 2021

### NEW FEATURES • (TRIA & TRIA+ PRODUCTION SERVERS)

#### 1. **VANC record and play in 1080i video standards (Tria & Tria+ with AVC-Intra Hardware Only)**

Added ability for record and playback of VANC data contained within the SDI video I/O pathways **in 1080i video standards**—so VANC data such as closed-captioning, HDR flags, etc. are preserved during base-band record and playback on the SDI video I/O pathways.

### BUGS FIXED • (TRIA & TRIA+ PRODUCTION SERVERS)

No Bug Fixes

## VERSION 7.1.14 – APRIL 2021

### NEW FEATURES • (TRIA & TRIA+ PRODUCTION SERVERS)

No New Features

### BUGS FIXED • (TRIA & TRIA+ PRODUCTION SERVERS)

#### 1. **Quad Viewer SDI OUT Display**

Fixed an issue where data overlaid onto the Quad Viewer SDI Output (i.e., Clip Name and Timecode) would not appear.

This bug was introduced in V7.1.13 software.



## VERSION 7.1.13 – NOVEMBER 2020

### NEW FEATURES • (TRIA & TRIA+ PRODUCTION SERVERS)

No New Features

### BUGS FIXED • (TRIA & TRIA+ PRODUCTION SERVERS)

#### 1. Video Server Products with AVC-Intra Video Hardware Initialization Error (Tria & Tria+ with AVC-Intra Hardware Only)

Fixed rare issue in which AVC-Intra video hardware that would *sometimes* not initialize at O/S restart and/or at power-on, resulting in 'no video channels'.

## VERSION 7.1.12 – SEPTEMBER 2020

### NEW FEATURES • (TRIA & TRIA+ PRODUCTION SERVERS)

No New Features

### BUGS FIXED • (TRIA & TRIA+ PRODUCTION SERVERS)

#### 1. Media File Import App Compatibility Fixes

Improved compatibility of certain media files codecs and wrappers during media file import transcoding while using the FFmpeg codec libraries.

## VERSION 7.1.11 – AUGUST 2020

### NEW FEATURES • (TRIA & TRIA+ PRODUCTION SERVERS)

No New Features. This release version number was for Mira replay systems.

### BUGS FIXED • (TRIA & TRIA+ PRODUCTION SERVERS)

No Bug Fixes. This release version number was for Mira replay systems.

## VERSION 7.1.10 – MARCH 2020

### NEW FEATURES • (TRIA & TRIA+ PRODUCTION SERVERS)

No New Features. This release version number was for 2RU Express video servers.

### BUGS FIXED • (TRIA & TRIA+ PRODUCTION SERVERS)

No Bug Fixes. This release version number was for 2RU Express video servers.



## VERSION 7.1.7 THROUGH VERSION 7.1.9

### NEW FEATURES • (TRIA & TRIA+ PRODUCTION SERVERS)

No New Features. These release version numbers were only for **Tria News** video servers.

### BUGS FIXED • (TRIA & TRIA+ PRODUCTION SERVERS)

No Bug Fixes. These release version numbers were only for **Tria News** video servers.

## VERSION 7.1.6 – AUGUST 2020

### NEW FEATURES • (TRIA & TRIA+ PRODUCTION SERVERS)

No New Features

### BUGS FIXED • (TRIA & TRIA+ PRODUCTION SERVERS)

No Bug Fixes. This release version number was only for **Mira+** replay system.

## VERSION 7.1.5 – NOVEMBER 2019

### NEW FEATURES • (TRIA & TRIA+ PRODUCTION SERVERS)

No New Features

### BUGS FIXED • (TRIA & TRIA+ PRODUCTION SERVERS)

2. **Fix for new Xilinx part used on AVC-Intra video boards in Mira and Tria platforms (Tria & Tria+ with AVC-Intra Hardware Only)**

Xilinx changed something subtle in the newest fab of their chips, which in turn could sometimes cause 'green artifacts' on some SDI video outputs.

## VERSION 7.1.4 – NOVEMBER 2019

### NEW FEATURES • (TRIA & TRIA+ PRODUCTION SERVERS)

No New Features

### BUGS FIXED • (TRIA & TRIA+ PRODUCTION SERVERS)

No Bug Fixes. This release version number was only for **Mira Express** replay system.



## VERSION 7.1.3 – OCTOBER 2019

### NEW FEATURES • (TRIA & TRIA+ PRODUCTION SERVERS)

No New Features

### BUGS FIXED • (TRIA & TRIA+ PRODUCTION SERVERS)

1. **Import of ANC data from MXF media files while operating in 59.94 frame-rate video standards (Tria & Tria+ with AVC-Intra Hardware Only)**

Corrected an issue when MXF media files were imported, ANC data present in the media file header were not imported.



## KNOWN ISSUES

### VERSION 8.3.1 – AUGUST 2022

No known issues.

### VERSION 8.3.0 – JUNE 2022

No known issues.

### VERSION 8.2.4 – JUNE 2022

No known issues.

### VERSION 8.2.3 — 8.2.1 (SKIPPED)

These version numbers were skipped.

### VERSION 8.2.2 – FEBRUARY 2022

#### 1. Missing Video Panes in DashBoard V9.5 and above

Video panes will not appear in a DashBoard panel running on the Tria video server itself. If the DashBoard app software version is V9.4 or below, the video panes operate properly.

## VERSION 7.1.14 – APRIL 2021

### 1. **Embedded Timecode sometimes Missing**

Embedded timecode of a clip may not appear within the SDI video output stream.  
(Issue resolved in V7.1.15 software release)



## GETTING HELP

Use the following link to view Ross Online Tria/Tria+ Help on the Web:

<https://help.rossvideo.com/tria/>

Our 24-hour hotline service provides access to technical expertise around the clock. After-sales service and technical support is provided directly by Ross Video personnel.

During business hours (Eastern Standard Time), technical support personnel are available by telephone.

After hours and on weekends, emergency technical support is available. A telephone-answering device will provide the names and phone numbers of technical support and field service personnel who are on call. These people are available to react to any problem and to do whatever is necessary to ensure customer satisfaction. For serious issues which need urgent attention and tracking, please ensure you are given a ticket number and refer to this in future communications.

Please refer to <https://support.rossvideo.com> for further information.

- **Technical Support: (+1) 613-686-1557**
- **Toll-free within North America: (+1) 833-859-0499**