

Ross Routing Switcher Firmware

This document summarizes the firmware for the Ross routing switcher products.

Document Revisions

Revision	ECO	Description	Date
01	013665	Initial release	09AUG2017
02	013789	Corrected a typo in the NK-3G144-X version number	07SEP2017
03	014139	Updated the software versions for the RCP-ME, RCP-QEx, Ultripower, Ultrix, and Ultricore. Added NK-GPI to the Control Products section.	20NOV2017
04	014617	Updated the software versions for RCP-ME, and RCP-QEx. Added ULTRIX-FR5 and ULTRIX-UCC to the Ultricore Series section.	12MAR2018
05	015057	Updated the software versions for the RCP-ME, RCP-QEx, Ultricore-CC, and ULTRIX-FRx.	07JUN2018
06	015606	Updated the software versions for the Ultripower, Ultricore-CC, and ULTRIX-FRx.	24SEP2018
07	015789	Updated the software versions for the Ultricore-CC, and ULTRIX-FRx.	06NOV2018
08	016029	Updated the software versions for the Ultricore-CC, and ULTRIX-FRx. Added Ulritouch to the Control Products section.	09JAN2019

Current Products

Product	Firmware Version	Release Date	Item#	ECO#
Ultracore Series				
Ultracore-CC	3v31	09JAN2019	2201ER-004-01	016005
ULTRIX-FR1, ULTRIX-FR2	3v31	09JAN2019	2101QR-20X-01	016005
ULTRIX-FR5	3v31	09JAN2019	2101QR-205-01	016005
ULTRIX-UCC	3v10	12MAR2018	2101QR-005-01	014632
Ultripower	SW: 1.32 FW: A016	27JUL2018 31MAY2017	2101ER-305-01 2101ER-304-02	015279 013248
DETOUR	1.09	7JUN2017	9201ER-001-01	013274
Control Products				
NK-NET	2.10	23DEC2016	2201ER-002-02	012433
NK-IPS	3.12	4AUG2016	2200ER-003-01	011686
NK-VRC	2.70	11AUG2015	9807ER-1009BRD-1-RC	009749
NK-3RD	2.13	1OCT2015	9807ER-1020-RC	010076
NK-GPI	2.05	16SEPT2016	9807ER-1008-01	014143
RCP-ME	1.71	06JUN2018	2201ER-003-01	015105
RCP-QE	1.71	06JUN2018	2201ER-003-01	015105
RCP-QE18	1.71	06JUN2018	2201ER-003-01	015105
RCP-QE36	1.71	06JUN2018	2201ER-003-01	015105
RCP-NK1	2.06	18OCT2012	2200ER-001-01	004661
RCP-NKM	2.21	27JUN2017	9806ER-1007-2-RC	011120
NK-SCP/A	2.12	3APR2007	9807ER-1007-1-RC	013586
NK-SCP/K2	2.12	13MAR2012	9807QR-1006BRD-1-RC	003192
Ulritouch	1.00	20NOV2018		
NK Series Routers				
NK-3G164	2.06	16NOV2012	2100ER-002-01	004836
NK-3G16	2.06	16NOV2012	2100ER-002-01	004836
NK-3G34	2.06	16NOV2012	2100ER-001-02	004836

Product	Firmware Version	Release Date	Item#	ECO#
NK-3G72	2.02	28APR2012	9807ER-0801-RC	003528
NK-3G144-X	2.12	31JUL2013	2500ER-200-01	006146
NK-A164	2.01	25OCT2012	9807ER-2002-4-01	004418
NK-A16	2.01	25OCT2012	9807ER-2002-01	004418
NK-A32	2.01	7SEPT2012	9807ER-2003-01	004488
NK-A64	2.01	4SETP2012	9807ER-0901-01	003908
NK-D164-110	2.01	1SEPT2012	9807ER-2010-4-01	004425
NK-D164-75	2.01	1SEPT2012	9807ER-2010-4-01	004425
NK-D16-110	2.01	2AUG2012	9807ER-2010-RC	003557
NK-D16-75	2.01	2AUG2012	9807ER-2010-RC	003557
NK-D32-110	2.01	7SETP2012	9807ER-2007-01	004147
NK-D32-75	2.01	7SEPT2012	9807ER-2007-01	004147
NK-D64-110	2.02	4SEPT2012	9807ER-0501-01	003908
NK-D64-75	2.02	4SEPT2012	9807ER-0501-01	003908
NK-M16	2.01	23OCT2012	9807ER-2009-01	004178
NK-M32	2.01	5SEPT2012	9807ER2008-01	004177

Obsolete Products

Product	Firmware Version	Release Date	Item#	ECO#
NK-V164	2.01	25OCT2012	9807E-2001-4-01	004418
NK-V16	2.01	25OCT2012	9807ER-2001-01	004418
NK-V32	2.01	7SEPT2012	9807ER-2005-01	004488
RCP-NKQ	2.22	27JUN2017	9806ER-1006-2-RC	011120