

Abekas **Tria News** Software Update Release Notes

Software Version: **V7.1.9**

Previous Version: **V7.1.6**

Document Revised: February 18, 2020



Bug Fixes | **Tria News** |

V7.1.9

1. **Only finite number of clips could be loaded/cued without restarting Abekas SE service.**

After very long periods of 24/7 operations, eventually none of the Tria News video channels can load/cue/play any clip from the server's internal storage or from external NAS. The only resolution to this issue was to restart the Abekas SE service, or reboot Windows O/S.

The **Tria News** 'Clip Counter Database' function code was faulty, and is fixed in V7.1.9 software.

This bug affected all clip operations performed via the **Tria Explorer** application and via **remote control** (via RS422 or Ethernet control from Streamline; Overdrive; Switcher; etc.).

New Features | **Tria News**

V7.1.9

No New Features

END of DOCUMENT