

机器人 - 有害物质的名称及含量表

Robotics - Table of hazardous substances' name and concentration

组件名称 Component Name	有害物质 Hazardous Substance					
	铅 (Pb)	汞 (Hg)	镉 (Cd)	六价铬 (Cr6+)	多溴联苯 (PBB)	多溴联苯醚 (PBDE)
印刷电路板组装 Printed Circuit Board Assembly	X	O	O	O	O	O
电缆及电缆组件 Cables and Cable Assemblies	X	O	O	O	O	O
电源 Power supply	X	O	O	O	O	O
滚珠轴承 Ball Bearing	X	O	O	O	O	O
机加工件 Machined Parts	X	O	O	O	O	O
紧固件 Fasteners	X	O	O	O	O	O
镜头 Lenses	X	O	X	O	O	O

此表是按照 SJ/T 11364 的规定编制。
This table is prepared in accordance with the provisions of SJ/T 11364.

O: 表示该有害物质在该部件所有均质材料中的含量均在 GB / T 26572 标准规定的限量要求以下
O: Indicates that said hazardous substance contained in all of the homogeneous materials for this part is below the limit requirement of GB/T 26572.

X: 表示该有害物质至少在该部件的某一均质材料中的含量超出 GB / T 26572 标准规定的限量要求
X: Indicates that said hazardous substance contained in at least one of the homogeneous materials used for this part is above the limit requirement of GB/T 26572.

