

## V6.3.6 Software Release Notes

This document describes all new software features and bug fixes since release of **V6.3.5 Software**, and applies to the following Abekas products: **Tria** production server; **Tria Express** clip server; **Tria News** playout server; **Mira** and **Mira Express** replay systems. Software **V6.3.0** was the first version supporting the **Tria News** playout server.

**PLEASE NOTE!** Some Abekas Products have been re-branded. Starting with software V6.3.5, all software installers are labeled according to the name of each Abekas server product. Therefore, the name of your product at the time of purchase may not be the same as the name of the correct software installer for your product. Please keep in mind: products formerly known as “**Mira** production server” are now “**Tria** production server,” products formerly known as “**Tria** clip server” are now “**Tria Express** clip server.”

### Bug Fixes

- Playback support for AVC-Intra 100 has been removed from Tria News playout server. AVC-Intra 100 was never advertised as a feature of the product; playback for the format was accidentally left in software for research and development purposes.
- Fan control software no longer operates based on product software installed, but rather auto-detects the fan controller board used by the system.
- For products that support clip networking, playlists now correctly display which clips are stored locally on the system media storage, and which clips are stored on a remote system.
- When operating in 4K, a bug has been fixed that prevented the option to output key signal as black or white from appearing in the engineering setup menu’s “Video” tab.
- For products that support 4K video/key, a bug has been fixed that prevented 4K videos from correctly importing and displaying a key signal.
- For products with AVC-Intra native recording hardware, a bug has been fixed that prevented importing single-frame sequence when using software importer.
- For products with AVC-Intra native recording hardware, a selection has been added to the importer that allows the “auto-start” feature to use the software importer.
- For products that support clip networking, a bug has been fixed that prevented clips from being dragged into a remote playlist.
- A bug has been fixed that limited the max clip length when the number of sectors exceeds 32 bits.
- For products that support transcoding exports, a bug has been fixed caused by out of order write commands to a NAS.
- For products with AVC-Intra native recording hardware, when opening the importer, there are no longer warnings about taking a channel offline.