

Ultrix Carbonite

Software Upgrade Information

V6.0.0

V6.0.0.6073 Software Updates

New Features (relative to Ultra 5.0):

- 2 MEs with 6 Keys and 4 MiniMEs with 2 Keys (HD)
- 2 MEs with 6 Keys and 2 MiniMEs with 2 Keys (UHD)
- 12 DVEs (HD)
- 6 DVEs (UHD)
- 4 Media-Store Channels (video+alpha) (HD and UHD).
- Device Configuration in DashBoard.
- Dedicated bank number displayed on Keypad touch screens (TD 2S and TD 3S).
- Source mnemonics on TD panels now flash when pushed. They will flash white if it performed an action and they will flash dark grey if no action is associated with them.
- DashBoard automatic discovery can now be turned off.
- DashBoard Help menu now includes Switcher Help, Panel Help, and Device Help.
- Moved Tally information from Inputs to Tally/GPIO tab.
- The user can copy keys from Live Assist.
- MultiViewers in UHD can be set to HD or UHD.
- SoftPanel has been upgraded to include 6 keys.

Fixed Bugs (that were in Ultra 5.0):

- 71977 – Media + Cut on the panel now saves the cut frame to the media-store database
- 64847 – CC Editor now properly works with Color Correctors in all formats
- 72346 – Fixed a memory leak with Play CC event
- 71357 – Sending a RossTalk CC command to run an empty CC will be ignored
- 71604 – CC Mnemonic mode is now in personality
- 67411 – GPIO types are now editable in the CC Editor
- 71667 – AMP servers now default EjtClp to Off